
PORM MR-AR (Revised 12/93)

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 Telephone: (801) 538-5340

Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

1.	Gener	eneral Information			
	1.	Report Time Period: From (mo./yr.) Jan. 1993 To (mo./yr.) Jan. 1994			
	2.	DOGM File Number (Mine No): ACT / 029 / 001			
	3.	Mine Name: Devils Slide Quarry			
	4.	Mineral(s) Mined (or permitted to mine): Limestone			
	5.	Type of mine			
	6.	Legal Description (Location of Lands Affected):			
		1/4,1/4, Section 19, Township 4N, Range 4E			
		1/4,1/4, Section 24, Township 4N, Range 3E			
		1/4,1/4, Section, Township, Range			
	7.	Name of Operator or Company:Holnam, Inc.			
	8. Permanent Street Address: Auxiliary Route #3				
		City, State, Zip: Morgan, Utah 84050			
		Phone: 801 829-6821			
	9.	9. Company Representative (or designated operator): Name:L. B. Giles			
	Title: Plant Manager				
		Business Address:Auxiliary Route #3			
		City, State, Zip: Morgan, Utah 84050			
		Phone: 801 829-6821			
		Please check if any of the above information has changed since previous year.			
II.	Minin	Mining and Reclamation			
	1.	Was the mine active during the past year? Yes ☒ No ☐			
	2.	If active, how much ore or mineral was mined? 543,530 Tons Limestone			
		5,975 Tons Sandstone			

	3.	How much additional acreage	was disturbed during the past year? <u>None</u>		
4. Briefly describe any new			ditional surface disturbances that occurred cription should include the type of work erial moved.		
		None - Benches in existing quarry area were mined.			
			Nana		
5.		How much acreage was reclaimed	during the past year? None		
Ċ		Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results. None			
7.	7. What is the total disturbed acreage at years end? 79 Acres				
8. Briefly summarize any mining and/or reclamation plans for the year.					
		Normal mining with tonnage requirements similar to 1992-1993 is			
			fic reclamation is planned until areas		
		become permanently inactive.			
NOTE:	<u>IOTE</u> : Section III., "Additional Information" applies only to <u>large mining operations</u> .				
III. <u>Additi</u>	ona	l Information			
1.		An updated surface facilities map should be attached if there have been significant changes since previous map was submitted.			
2.	 Any monitoring results or other reports that are required under the terms of the approved not intention should also be attached. 				
IV. Signat	ure	Requirement			
I h	erel	by certify that the foregoing is true	and correct.		
		Name (Typed or Print):	L. B. GILES		
		Title of Operator:	Plant Manager		
		Signature of Operator:			
		Date:	January 14, 1994		

Devil's Slide Plant 6055 E. Croydon Road Auxiliary Route 3 Morgan, Utah 84050 801/829-6821 Fax 801/829-6383

HOLNAM INC

January 14, 1994

Mr. D. Wayne Hedburg, Permit Supervisor Utah Department of Natural Resources Division of Gas, Oil and Mining 3 Triad Center Suite 350 Salt Lake City, Utah 84180-1203



JAN 1 9 1994

DIVISION OF OIL, GAS & MINING

Dear Mr. Hedburg,

Enclosed are the annual mining operation reports for our Devils Slide and Poverty Point quarries for 1993/1994.

If any further information is needed, please call or visit.

Sincerely,

L. B. Giles Plant Manager

LBG/y

Enclosure

cc: Roy Steinmier K. George